

Intel[®] Vision Accelerator Design with Intel[®] Movidius[™] Myriad[™] VPU

Errata

September 2019



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting: <http://www.intel.com/design/literature.htm>

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at <http://www.intel.com/> or from the OEM or retailer.

Intel, Movidius, Myriad, and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2019, Intel Corporation. All rights reserved.




Contents

1.0 Errata List	5
------------------------------	----------

Tables

Table 1. Scheduler Overview	5
-----------------------------------	---



Revision History

Date	Revision	Description
September 2019	0.5	Initial release.




1.0 Errata List

HDDL Errata that list out all known issues and limitations with symptoms and work-arounds

Table 1. USB device read descriptor failure Errata

Name	USB device read descriptor failure.
Hardware add-on Card	HDDL-L, HDDL-R cards from any vendors.
Hardware Host system	Any host system with Core, Atom or Xeon CPU.
Software	Windows, Linux, OpenVino 2019'R1 and later.
Symptoms	<p>BIOS ROM stage takes significantly more time (1-2 minutes more to the regular time without HDDL card installed) to move to OS boot. When OS booted,</p> <p>In Linux:</p> <ul style="list-style-type: none"> • when lsusb command invoked there were no Myriad X devices (ID 03e7:2485) enumerated in the list. • dmesg log has multiple error lines for " usb X-Y: device descriptor read/64, error -110". <p>In Windows:</p> <ul style="list-style-type: none"> • In Device Manager there will be 8 unknown USB devices in the list with "USB descriptor request failed".
Description	<p>The USB specification states that the String Descriptor about language supported by the USB device should be retrievable from the USB device by the software in 2- or 4- bytes formats. But, the current Myriad™ X ROM firmware only supports the 4-bytes format, which can cause a USB babble error if the software expects only a 2-bytes return value.</p> <p>The fix was implemented in Intel BIOS reference code, but it integration into System BIOS for a particular system depends on BIOS vendor.</p>
Workaround solution	<p>BIOS: Modify the UEFI BIOS code and send the request command to get the first FOUR bytes (bLength, bDescriptorType and wLANGID[0]), instead</p>



	<p>of the first TWO bytes. With the change, the USB babble error does not occur and the first 4-bytes data can be returned successfully.</p> <p>Software:</p> <ul style="list-style-type: none">• Call PCI reset for PCI root device on HDDL card use bsl_reset tool before run hddl service.
Reference	<h3>Intel UEFI Workaround</h3> <p>Modify the Intel reference UEFI code and send the request command to get the first FOUR bytes (bLength, bDescriptorType and wLANGID[0]), instead of the first TWO bytes. With the change, the USB babble error does not occur and the first 4-bytes data can be returned successfully.</p> <p>File name and path of the Intel UEFI source code to be modified:</p> <p>PlatformNamePkg\Override\MdeModulePkg\Bus\Usb\UsbBusDxe\UsbDesc.c</p> <p>Before:</p> <pre>611 EFI_USB_STRING_DESCRIPTOR * 612 UsbGetOneString (613 IN USB_DEVICE *UsbDev, 614 IN UINT8 Index, 615 IN UINT16 LangId 616) 617 { 618 EFI_USB_STRING_DESCRIPTOR Desc; 619 EFI_STATUS Status; 620 UINT8 *Buf; 621 622 // 623 // First get two bytes which contains the string length. 624 // 625 Status = UsbCtrlGetDesc (UsbDev, USB_DESC_TYPE_STRING, Index, LangId, &Desc, 2); 626 627 if (EFI_ERROR (Status)) { 628 return NULL; 629 } 630 631 Buf = AllocateZeroPool (Desc.Length);</pre>



```

After:
611 EFI_USB_STRING_DESCRIPTOR *
612 UsbGetOneString (
613     IN     USB_DEVICE    *UsbDev,
614     IN     UINT8         Index,
615     IN     UINT16        LangId
616 )
617 {
618     EFI_USB_STRING_DESCRIPTOR Desc;
619     EFI_STATUS                 Status;
620     UINT8                      *Buf;
621
622     //
623     // First get four bytes which contains the string length.
624     //
625     Status = UsbCtrlGetDesc (UsbDev, USB_DESC_TYPE_STRING, Index, LangId, &Desc, sizeof (EFI_USB
626
627     if (EFI_ERROR (Status)) {
628         return NULL;
629     }
630
631     Buf = AllocateZeroPool (Desc.Length);
    
```

Table 2. Interrupt of autoboot.exe caused failure to enumerate Myriad X nodes Errata

Name	Interrupt of autoboot.exe caused failure to enumerate Myriad X nodes.
Hardware add-on Card	HDDL-L and HDDL-R from any vendor.
Hardware Host system	Any Windows based system host.
Software	Windows, OpenVino R1'2019 and later releases.
Symptoms	Autoboot.exe service cannot enumerate Myriad X devices.
Description	When hddldaemon.exe starts it will invoke autoboot.exe. If autoboot.exe is interrupted by Ctrl-C, the service will be restarted automatically but in this case will not be able to enumerate Myriad X USB devices.
Workaround solution	Do not use Ctrl-C to close autoboot.exe console app or interrupt autoboot process and wait autoboot finished by defined timeout. In case it happened, stop and restart hddldaemon service again.
Reference	




Table 3. Host system with installed HDDL-R card reboot occasionally Errata

Name	Host system with installed HDDL-R card reboot occasionally.
Hardware add-on Card	HDDL-L and HDDL-R from any vendor, when configured use I2C IO expander to reset Myriad X node.
Hardware Host system	Any Windows or Linux host system with SMBUS supported on Pci-E slot.
Software	Linux, Windows, OpenVino R1'2019 and later releases.
Symptoms	Occasional host system restart.
Description	Issue might cause by a conflict of I2C expander address on SMBUS.
Workaround solution	Detect if there is any I2C device on SMBUS with 0x20-0x27 addresses, if yes, change the DIP switch on the PCIE card to avoid the address conflict on SMBUS.
Reference	

Table 4. HDDL-R card USB devices are not found after system boot up Errata

Name	HDDL-R card USB devices are not found after system boot up.
Hardware add-on Card	HDDL-R with Pericom G608 PCIe switch.
Hardware Host system	Any Windows or Linux host system.
Software	Linux, Windows, OpenVino R1'2019 and later.
Symptoms	Myriad X on HDDL-R card USB devices (Eight MA2485 and four USB hubs) are not enumerated after OS boot.
Description	This is caused by the Pericom G608 PCIe switch, which occurs when the motherboard's UEFI BIOS or OS program enables the ACS P2P Request Redirect the PCIe switch function.
Workaround solution	Disable ACS P2P Request Redirect in BIOS Implement workaround at OS level, following Pericom switch manufacturer's recommendation.




<p>Reference</p>	<p>Executing the Workaround on Ubuntu* OS</p> <p>This script is used to resolve the issue on the Ubuntu* OS.</p> <p>Script Path</p> <p><code>\${HDDL_INSTALL_DIR}/hddl-bsl/src/setup_tools/pericom_g608_linux/install.sh</code></p> <p>HDDL_INSTALL_DIR environment variable is set when OpenVINO™ is installed.</p> <p>Installation</p> <p>The install.sh script needs to be executed manually after the OpenVINO™ installation. Once this script is executed, the workaround will take effect automatically after each OS boot.</p> <p>Notice</p> <p>This script disables the ACS P2P Request Redirect Registers (CFG Offset 224h, bit18) of the four downstream ports on all of the Pericom G608 PCIe switches existing on the system. The script also does not check whether the PCIe switch is embedded in the Intel® Vision Accelerator Design with Intel® Movidius™ VPUs board.</p> <p>Executing the Workaround on Windows* OS</p> <p>Script Path</p> <p><code>\${HDDL_INSTALL_DIR}/hddl-bsl/src/setup_tools/pericom_g608_win/install.ps1</code></p> <p>HDDL_INSTALL_DIR environment variable is set when install OpenVINO.</p> <p>Installation</p> <p>Right click on the install.ps1 script, and select Run with PowerShell. Once installed, the workaround will take effect automatically after each OS boot.</p>
------------------	--



	<p>Notice</p> <p>This script disables the ACS P2P Request Redirect Registers by invoking the application provided by the Pericom.</p> <p>The patch can be downloaded from the following link: https://www.diodes.com/products/connectivity-and-timing/pcie-packet-switchbridges/pcie-switch/#tab-finder</p> <ul style="list-style-type: none">• PCIe 2.1 Packet Switch Selector Guide• Register Programming PCIEdit (3MB Zip File)• Patch Program to Disable ACS P2P Request Redirect Function (Windows 32-bit File)• Perspective Blog: In-Car Connectivity is Changing the Driving Experience for the Better
--	---

Table 5. Multiple reset requests during HDDL-R card operation might cause blocking SMBUS transaction Errata.

Name	Multiple resets requests during HDDL-R card operation might cause blocking SMBUS transaction.
Hardware add-on Card	HDDL-R with I2C IO expander.
Hardware Host system	Host systems with SMBUS enabled on PCI-E slot.
Software	Linux, OpenVino R1'2019 and later when configured using I2C IO expander to reset Myriad X nodes.
Symptoms	When the HDDL card is configured using IO expander to handle Myriad X devices' reset on the card and multiple resets (30 or more) of Myriad X devices occurred over the HDDL card operation time. The I2C transaction could be blocked on SMBUS. In result of this multiple error messages will appear in the hddldaemon log and one or more Myriad X node on HDDL card will not be available to take inference payload. If hddldaemon service being restarted, it will fail to find reset devise and messages will appeared in the log [BSL] No device found ERROR[AutoBoot.cpp:470] Error: HDDL hardware initialization failed, exits now.



Description	
Workaround solution	To bring system in normal operation the cold system reset is required. Reconfigure system use USB reset path through USB device on HDDL-R card. Please refer to HDDL-R card manufacture
Reference	